



WO# 844175598

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175598	Activity: SCC	CLEAN CATCH BASIN/INLET	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431600			
Address:	48 ST			
Qualifier:	ON 65 FROM 37TH AV 37TH AV/NORTHERN BL			Map# QH137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 65 FROM 37TH AV 37TH AV/NORTHERN BL		District: 844175598	
	ON 65 FROM 37TH AV 37TH AV/NORTHERN BL			
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Primary Caller: [REDACTED] Call Date: 07-02-2018 05:15 PM
Address: [REDACTED]
Day Phone: [REDACTED]
Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: Clean Catch Basin/Inlet comments

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175599

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175599	Activity: SCC	CLEAN CATCH BASIN/INLET	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431607			
Address:	48 ST			
Qualifier:	ON 0 FROM 37TH AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON65 FROM 37TH AV37TH AV/NORTHERN BLON65 FROM 37TH AV37TH AV/NORTHERN BL		District: 844175599	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:			Permit#	
Project:			Completed: 07-03-2018 12:04 PM	
Source:			Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: Clean Catch Basin/Inlet comments

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175600

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175600	Activity: SCC	CLEAN CATCH BASIN/INLET	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431606			
Address:	48 ST			
Qualifier:	ON 40 FROM 37TH AV BARNETT AV/37TH AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON65 FROM 37TH AV37TH AV/NORTHERN BLON65 FROM 37TH AV37TH AV/NORTHERN BL		District: 844175600	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:			Permit#	
Project:			Completed: 07-03-2018 12:04 PM	
Source:			Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: Clean Catch Basin/Inlet comments

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175601

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175601	Activity: SCC	CLEAN CATCH BASIN/INLET	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431499			
Address:	48 ST			
Qualifier:	ON 60 FROM NORTHERN BL NORTHERN BL/37TH AV			Map# QH137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON65 FROM 37TH AV37TH AV/NORTHERN BLON65 FROM 37TH AV37TH AV/NORTHERN BL		District: 844175601	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI		Call Date: 07-02-2018 05:15 PM	
Address:				
Day Phone:	(718)595-5816			



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: Clean Catch Basin/Inlet comments

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175602

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175602	Activity: SCC	CLEAN CATCH BASIN/INLET	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431601			
Address:	48 ST			
Qualifier:	ON 20 FROM 37TH AV 37TH AV/NORTHERN BL			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON65 FROM 37TH AV37TH AV/NORTHERN BL ON65 FROM 37TH AV37TH AV/NORTHERN BL		District: 844175602	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: Clean Catch Basin/Inlet comments

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175603

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175603	Activity: SCC	CLEAN CATCH BASIN/INLET	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB432614			
Address:	BARNETT AVE			
Qualifier:	OPPOSITE 18 FROM BARNETT AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 402 QUEENS COMMUNITY BOARD 2	
Location :	Asset Location Comments: ON65 FROM 37TH AV37TH AV/NORTHERN BLON65 FROM 37TH AV37TH AV/NORTHERN BL		District: 844175603	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: Clean Catch Basin/Inlet comments

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175604

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175604	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431499			
Address:	48 ST			
Qualifier:	ON 60 FROM NORTHERN BL NORTHERN BL/37TH AV			Map# QH137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 60 FROM NORTHERN BL NORTHERN BL/37TH AV		District: 844175604	
	ON 60 FROM NORTHERN BL NORTHERN BL/37TH AV			
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261 During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES 07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#464/593 ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601, 431603, 431604, 431606, 431607, 431608 CB #431609, 432613, 432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTAL CB#431602, 431605, 432614 AND 431499 ARE OPEN CURB PIECE CATCH BASINS FOUR (4) IN TOTAL CB#431601, 431602, 431603, 431604, 431605, 431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO) STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATER AND CLEAN AND CLEAR CB CONN NO. 431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUE INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603, 431604, 431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFF AND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAY INSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463 CLEANED FOUR (4) BASINS TO THE BOTTOM FUNCTIONING OTHERS C.O.B. AT THIS TIME INSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463 REPAIR BASIN NO. 431608 AT 48 ST AND 37 AVE REMOVE ASPHALT AND OLD CASTING INSIDE UNIT NO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORK INSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804 CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATER INSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175605

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175605	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431600			
Address:	48 ST			
Qualifier:	ON 65 FROM 37TH AV 37TH AV/NORTHERN BL			Map# QH137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON60 FROM NORTHERN BLNORTHERN BL/37TH AVON60 FROM NORTHERN BLNORTHERN BL/37TH AV		District: 844175605	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments
----------	-------------	-----------	--------	----------

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM

**Custlog History**

Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 31SCREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175606

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175606	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431607			
Address:	48 ST			
Qualifier:	ON 0 FROM 37TH AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON60 FROM NORTHERN BLNORTHERN BL/37TH AVON60 FROM NORTHERN BLNORTHERN BL/37TH AV		District: 844175606	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175607

Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844175607	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431606			
Address:	48 ST			
Qualifier:	ON 40 FROM 37TH AV BARNETT AV/37TH AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON60 FROM NORTHERN BLNORTHERN BL/37TH AVON60 FROM NORTHERN BLNORTHERN BL/37TH AV		District: 844175607	
Initiated By:	7060	YAP, RICHMANN	Initiated: 07-03-2018 07:59 AM	Scheduled: N/A
Assigned To:	10026	FURCI, DOMINICK	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S3	SEWER- 3 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-03-2018 12:05 PM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		

WO Comments: 07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset